MASTER COACHBUILDER

INFORMATION UPDATE

Date: September 30, 2014
Bulletin Number: XTS 37
Subject: New Underbody Braces on 2015 XTSPRO Vehicles

New underbody structure has been added to 2015MY XTSPRO vehicles (B9Q hearse, V4U limo and W30 extended sedan). See pictures in attached file. These bolt on braces must not be removed or altered. They are necessary to ensure compliance with crashworthiness requirements.

Please contact Ray Bush with any questions.